

Department of Energy

ROCKY FLATS FIELD OFFICE 10808 HIGHWAY 93, UNIT A GOLDEN, COLORADO 80403-8200

JUN 0 7 2000

00-DOE-02698

Mr. Steven Gunderson Rocky Flats Cleanup Agreement Coordinator Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Dear Mr. Gunderson:

Enclosed please find a copy of the "Sampling and Analysis Plan For The D&D Ground Water Monitoring of Buildings 707, 776/777, 371/374, 865 and 883." The Department of Energy requests that the document be reviewed with any comments by June 15, 2000. This plan is being submitted in support of the Decommissioning and Demolition monitoring requirements in the Integrated Monitoring Plan. A copy is also being sent to the U.S. Environmental Protection Agency, Region VIII.

If you should have any questions related to this Sampling and Analysis Plan, please contact Norma I. Castaneda at (303)966-4226 or contact me at (303)966-5918.

Joseph A. Legare Assistant Manager

for Environment and Infrastructure

Enclosure

cc w/ Enclosure:

C. Spreng, CDPHE

G. Kleeman, EPA

Administrative Record

cc w/o Enclosure:

J. Rampe, DAMEI, RFFO

R. Tyler, ERWM, RFFO

N. Castaneda, ERWM, RFFO

R. Nininger, K-H

T. Rehder, EPA

